


North East Roofing Private Limited

Annex-1


Air Monitoring Data Half-Yearly

Month	PM2.5 ($\mu\text{g}/\text{m}^3$)					PM10 ($\mu\text{g}/\text{m}^3$)				
	Near NERPL	At Scrap Sheet Yard	Behind CGL Unit	Mobile	Max Limit	Near NERPL	At Scrap Sheet Yard	Behind CGL Unit	Mobile	Max Limit
Apr --21	27.21	28.4	26.82	26.98	60	57.33	57.04	56.88	56.9	100
May-21	27.14	27.05	26.9	27.14	60	57.31	57.15	55.022	53.158	100
Jun-21	27.39	27.1	26.98	27.39	60	57.31	57.36	56.83	57.31	100
Jul-21	27.29	27.31	26.76	27.39	60	57.18	57.35	56.69	57.31	100
Aug-21	27.13	27.13	27.05	27.05	60	57.08	56.95	56.78	56.78	100
Sep-21	27.05	27	26.69	27.25	60	56.78	57.06	56.56	56.9	100

Ambient Air Monitoring Results (PM 2.5)



Ambient Air Monitoring Results (PM10)



Handwritten signature/initials

Report No.: ENV/ARL-NERPL/GHY/21-22/AA-09/01

Date : 27/09/2021

Order No.:

Date :

Report Issued To : **ASSAM ROOFING LIMITED/NORTH EAST ROOFING LIMITED**
Bonda, Narengi, Guwahati – 26 (Assam)**AMBIENT AIR QUALITY TEST RESULTS**

Sl. No.	LOCATION(S) ↓	Date of Sampling	PM 2.5 ($\mu\text{g}/\text{m}^3$)	PM 10 ($\mu\text{g}/\text{m}^3$)	SO ₂ ($\mu\text{g}/\text{m}^3$)	NO ₂ ($\mu\text{g}/\text{m}^3$)
	LIMIT(S) →		60	100	80	80
01	Near Security Main Gate (26.18542, 91.84139)	08.09.2021	29.6	67.6	8.6	14.8
02	In front of PDP Gate (26.18374, 91.84065)	09.09.2021	32.4	70.5	8.2	15.4
03	Back Side of Canteen (26.18604, 91.8421)	09.09.2021	25.7	62.9	7.9	13.5

Analysis Protocol: IS 5182

Checked By: Mr. Pankaj Baroi, **ENVIROCON**


- NOTE:**
1. Results reported are valid at the time of and under the prevailing conditions of measurement.
 2. Results refer only to the particular parameters tested.
 3. This test report shall not be reproduced except in full, without the written permission of ENVIROCON, I.O.C.L (AOD) New Market, Digboi – 786171, Assam.

Core Services: Environmental Monitoring & Data Generation, EIA & EMP, Environmental Audit & Allied Environmental Management jobs
Associate Services: Certification by Competent Person (CIF), NDT, Hydraulic Testing, Chartered Engineer Services etc.


North East Roofing Pvt. Limited

Stack Monitoring Data						DATE OF SAMPLING		
Month	Fibre Dust Collector Stack (S1) Total Dust	Max Limit	Cement Dust Collector Stack (S2), Total Dust (mg/Nm ³)	Fly-Ash Dust Collector Stack (S3), Total Dust	Max Limit	Fibre Dust Collector Stack (S1)	Cement Dust Collector Stack (S2)	Fly-Ash Dust Collector Stack (S3)
Apr-21	0.48	2	47.28	50.05	100	7/4/2021	8/4/2021	9/4/2021
May-21	0.57	2	41.45	42.44	100	10/5/2021	10/5/2021	11/5/2021
Jun-21	0.61	2	38.45	76.23	100	18/6/2020	17/6/2021	13/06/2021
Jul-21	0.56	2	42.95	51.32	100	15/7/2021	21/7/2021	21/7/2021
Aug-21	0.55	2	50.48	42.58	100	22/08/2021	17/08/2021	24/08/2021
Sep-21	0.51	2	43.42	46.23	100	28/09/2021	16/09/2021	19/09/2021


Stack Monitoring - Fibre Dust Collector Stack



Stack Monitoring - Cement Dust Collector Stack



Stack Monitoring - Fly-Ash Dust Collector Stack



File